

Work Order ID 59389

Thursday, June 03, 2010 11:18:46 AM



Page 1

Item ID: D3161-7

Accept



Setup Start



Revision ID:

Item Name: Hinge 14.0"

Stop



Start Date: 6/3/2010 Start Qty: 13.00



Cust Item ID:

Required Date: 6/14/2010 Req'd Qty: 13.00

Customer:

Reference:

Approvals:

Process Plan:

[Signature]

Date: 10-6-03

Tooling:

Date:

Run Start



QC:

Date:

SPC (Y/N):

Date:

Stop



Sequence ID/
Work Center ID

Operation
Description

Set Up/
Run Hours

Tool ID

Tool #

Plan
Code

Accept
Qty

Reject
Qty

Reject
Number

Insp.
Stamp

Draw Nbr

Revision Nbr

D3161

Rev A2

100

0.00



Small Fab

Small Fab

Memo

0.00

Small Fab

(1) 72" Hinge makes (5) D3161-7 parts at 14" long ☐ Cut to length as per Dwg D3161

[Signature] 10/06/03 (13)

110

QC5- Inspect part completeness to step on W/O

0.00



QC

Memo

0.00

Quality Control

[Signature] 10/06/03 (13)

120

Identify as per dwg & Stock Location: *LA*

0.00



Packaging

Memo

0.00

Packaging

[Signature] 10/06/03 (13)

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Work Order ID 59389

Thursday, June 03, 2010 11:18:46 AM



Page 2

Item ID: D3161-7

Accept



Setup Start



Revision ID:

Stop



Item Name: Hinge 14.0"

Start Date: 6/3/2010 Start Qty: 13.00



Cust Item ID:

Required Date: 6/14/2010 Req'd Qty: 13.00



Customer:

Reference:

Approvals: Process Plan: _____ Date: _____ Tooling: _____ Date: _____

Run Start



QC: _____ Date: _____ SPC (Y/N): _____ Date: _____

Stop

Sequence ID/
Work Center IDOperation
DescriptionSet Up/
Run Hours

Tool ID

Tool #

Plan
CodeAccept
QtyReject
QtyReject
NumberInsp.
Stamp

130

QC21- Final Inspection - Work Order Release

0.00



QC

Memo

0.00

Quality Control

10/06/04

Pl 10-6-03
13

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Picklist Print

Thursday, June 03, 2010 11:18:49 AM

Page 1

Work Order ID: 59389



Parent Item: D3161-7



Parent Item Name: Hinge 14.0"


Start Date: 6/3/2010

Required Date: 6/14/2010

Comments: IPP ☐ A ☐ 04.08.24 ☐ New Issue ☐ KJ/JLM ☐

Start Qty: 13.00

Required Qty: 13.00

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
MS20257-3-7200  Piano Hinge		Purchased	No			100	f	17.3100	1.2	15.6			



Handwritten signature
6/3/10

15.6

Location

ST489A

113368

Loc Qty

17.31

17.31

Loc Code

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			


NOTE: Date & initial all entries



DESIGN #	DRAWN BY #	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
CHECKED KF	APPROVED #	DRAWING NO. D3161	REV. A SHEET 1 OF 1
DATE 02.04.24		TITLE HINGE	SCALE NTS
A	02.04.24	NEW ISSUE	
A1	04.02.27	ADDED D3161-5	
A2	04.06.30	ADD D3161-7 & D3161-9	

RELEASED
02.04.24

P/N	LENGTH 'L'	DESCRIPTION
D3161-1	13.5"	HINGE (REPLACES MS20257-3-13.5 ON D2183)
D3161-3	15.0"	HINGE (REPLACES MS20257-3-15.0 ON D2950-041)
D3161-5	9.9"	HINGE
D3161-7	14.0"	HINGE
D3161-9	17.0"	HINGE



SHOP COPY
RETURN TO
ENGINEERING
UNCONTROLLED COPY
SUBJECT TO AMENDMENT
WITHOUT NOTICE
WORK ORDER
NO. 59389

10-4-03

NOTES:

- ① MAKE FROM MS20257-3-7200 HINGE

Copyright © 2002 by DART AEROSPACE LTD

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries